FIG. 1A






FIG. 1B

107
108
105
104
103
109








FIG. 2C

FIG. 3A




FIG. 3B

207
208
205
204
203
202




FIG. 5A






FIG. 5B





ELEMENT 2

FIG. 7A




FIG. 7B

407
408
408
404
404
409
400
400




FIG. 9A





FIG. 9B

507
508
505
504
503
509






FIG. 11C




FIG. 12

704

703

702

701

FIG. 13




FIG. 14





FIG. 15

PHOTOABSORBING MEDIUM AND WELDING STABILITY



NO MEDIUM

FIG. 16




FIG. 17








FIG. 18A












FIG. 20




FIG. 21





FIG. 22



S